











✓ Jan	Feb	Mar	Apr	May	Jun	✓ Jul	Aug	Sep	Oct	Nov	Dec
-------	-----	-----	-----	-----	-----	-------	-----	-----	-----	-----	-----



Keylite PVC Roof Windows Maintenance and Service Kit Instructions
















2017A



Scan QR code to see
more informations about
Maintenance and Service
Keylite Windows

Keylite Roof Windows NI
www.keylitteroofwindows.com



Firefighting Measures

Grease:

Suitable extinguishing media includes water spray, alcohol-resistant foam and CO₂.

Spillage Measures

Grease:

Soak up with inert absorbent material.

Ecological Information

Grease:

Not readily biodegradable.

H-statements

Grease:

H304 May be fatal if swallowed and enters airways.
H315 Causes skin irritation. H318 Causes serious eye damage. H335 May cause respiratory irritation.